i.			50	11-	2	-					
Work Order II Friday, May 24, 2013	D 102097-2	H 10	*1	020	97*		5	hip	Wed	n	Page
Item ID: D313 Revision ID: Item Name: Guide Start Date: 5/24/ Required Date: 5/29/ Reference:	e /2013 Start Qty: 70.00	*70* *70*	Accept 66 Ac	*	Cust Item I		100)*	Setup Star Stop	IV	IS1* IS2*
Approvals: Pro-	cess Plan: MF	Date: 3-5-9	Tooling: SPC (Y/N):	(Z)		ite:		1	Run Star Stop		R1*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hou	urs	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D3137	Revision Nbr Rev F	1	0.00		10 1 10 10 10 10 10 10 10 10 10 10 10 10		Code	4.3	20	Walifor	Statup
100 Bandsaw Jeaspa Bandsaw	BAND SAW Memo Cut Blanks.	Blank size: 1.250" x .750"	0.00	JFC MH	9013 5013	-05:25		70	φ		
110 HAAS 1 HAAS CNC vertical machin	HAAS CNC VERTICAL Memo 1-Machine a	MACHINING #1 s per Folio FA242 & Dw	0.00 0.00 g D31372-Deburr	SFC	2013-(05-28		Ch	φ	* L	

0.00

0.00

OFE 2013-05-28

66

120

120

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Memo

Work Order ID 102097

Friday, May 24	, 2013 11:08	8:56 AM	Fight.	- 4	102	1197"					Page 2
Item ID: Revision ID: Item Name: Start Date: Required Date: Reference:	D3137-3 Guide 5/24/2013 : 5/29/2013	Start Qty: 70.00 Req'd Qty: 70.00		*70* *70*	Accept	*N900 Cust Item I Customer:		N* Set	up Start Stop		S1* S2*
Approvals:	Process Pl QC:	an:	Date:	791	Tooling: SPC (Y/N):		ite:	Rui	Start Stop	*N	R1* R2*
Sequence ID/ Work Center II 130 *130* QC Quality Control 140 *140* Packaging Packaging	D	Operation Description QC8- Inspect parts - secon Memo Identify as per dwg & Stoo		87.33	Set Up/ Run Hours 0.00 0.00 0.00	Tool ID	Tool # Plan Code		Qty 1	Reject Number	Insp. Stamp
*150 *150* QC Quality Control		QC21- Final Inspection - V	Vork Order	Release	0.00			MLS	13-	13-5	

Friday, May 24, 2013 11:08:55 AM

Work Order ID:

102097

Parent Item:

D3137-3

Parent Item Name:

Guide

Start Date: 5/24/2013

Required Date: 5/29/2013

Start Qty: 70.00

Required Qty: 70.00

Comments:

IPP Rev: A02.05.29New IssueNG

IPP Rev:B 08-05-23 revE as per dwg DD verified by:EC

IPP Rev c 08.07.03 ECN1207

EC verified by DD

Component Item	ID/
Item Name	
	_

Replacement Item ID

Mfg/ Purch

Bin Primary Item Location Last Location

Route Seq ID

Unit of Measure Hand

Qty on

Qty per Kit Total

Qty Issued Qty

Date Issued

Status

MDELRINBO.75X1.250

Purchased

No

100

Loc Code

5.7168

0.0791

5.8284211

Delrin Bar

Location MAT018

117985 119133

120035

Loc Qty 5.716812 1.0056


0.008 0.001476

0.031736 4.67

OFC 2013:05-25.

(11x) -792

MDELRINB .75 x 1.00



DART AEROSPACE LTD	Work Order:	102097
Description: Guide	Part Number:	D3137-3
Inspection Dwg: D3137 Rev: F		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.175	+/-0.010	0.176	~		Calpin	3FC-01
Ø0.257	+0.005/-0.000	0.259	/			11
Ø0.65 x 100°	+/-0.030	0.65×1000	V		t,	
0.425	+/-0.010	0.424	V	Sale Mi		n va
0.550	+/-0.010	0.550	V	nien,	11	-
1.100	+/-0.010	1,101	~	1 Mil	1.1	ĩ,
0.470	+/-0.010	0.472	1		(,	٠,
0.850	+/-0.010	0.851	V		ts	1,
0.143	+/-0.010	0.143	✓			
			12			
			,c			

Measured by: OFC	Audited by:	Po	Prototype Approval:	N/A
Date: 2013-05-28	Date:	13/05/29	Date:	N/A

Date	Change	Revised by	Approved
03.11.27	New Issue		Approved
04.11.12	0.175 was 0.145 & Ø0.65 x 100° was Ø0.75 x 100°		
06.03.15	Dwg Rev updated		Tu V
		1.0	N
	03.11.27 04.11.12 06.03.15	Date Change 03.11.27 New Issue 04.11.12 0.175 was 0.145 & Ø0.65 x 100° was Ø0.75 x 100° 06.03.15 Dwg Rev updated 08.12.02 Dwg Rev updated	03.11.27 New Issue KJ/RF 04.11.12 0.175 was 0.145 & Ø0.65 x 100° was Ø0.75 x 100° KJ/JLM 06.03.15 Dwg Rev updated KJ/JLM